BRUHAT BANGALORE MAHANGARA PALIKE

Inspection Report

1	Name Of Work:	Construction of First Floor Office for AEE (Yeshwanthpur) at JP Park Swimming Pool Parking area in ward no 17
2	Administration Approval & Date	JC/RRN/AS/2757/2013-14 Dtd: 18.01.2014
3	Technical Sanction Estimate No. & Date	Modified TS: CE/RRN/TS/111/2016-17 Dtd: 28.06.2016
4	Estimate Amount	19,95,000/-
5	Job Code No.	017-14-000062
6	P-Code	P-2434 Development works for Bangalore City
7	Agreement No and Date:	EE/RRND/Agmt/277/13-14 Dtd: 22.02.2014
8	Work order Number & Date	EE/RRND/WO/277/13-14 Dtd: 22.02.2014
9	Contract Amount as per Agreement	Rs. 20,71,836/-
10	Bill Amount	Rs. 20,71,708/-
11	B.R No. & Date	152/16-17 Dtd: 28.09.2016
12	Agency	M/s Vrushabhadri Constructions
13	M.B. Number & Page No. of Measurement records	3923/15-16 Page No 392216 to 392221
14	Date of Inspection	13.09.2017
15	Enclosures	Number of photos taken during inspection
16	Inspection Report	I have Inspected the above site Location along with the Concerned person, as per EE(RRND) Letter No EE/RRN/JPR/414/A/17-18 Dated 1-9-2017. The measurements of the Items indicated in the MB/XL sheets, which are Susceptible for measurements have been checked and found to be Satisfactory

13/9/2017

(R. Sathyanarayana)
Inspection Report Officer.

EE (RRN) Division, RR Nagara Zone.
ರಾಜರಾಜೇಶ್ವರಿ ನಗರ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬೆಂಗಳೂರು-560 072

Scanned by CamScanner